

Manuscript Details

Manuscript number	EFA_2018_415_R1
Title	FAILURE ANALYSIS OF WORN VALVE TRAIN COMPONENTS OF A FOUR-CYLINDER DIESEL ENGINE
Article type	Research Paper

Abstract

This work investigates the causes of excessive wear occurring at the rocker arm/pushrod and rocker arm/valve interfaces of a diesel engine for industrial cleaning machines, after only 1000 hours of engine operation. In this engine, the recent replacement of tappets by hydraulic valve lifters not only reduced the running time but also required supplementary maintenance. The chemical composition of the worn components was verified by optical emission spectroscopy. The microstructures, mechanical properties and surface textures were determined by optical microscopy, Vickers hardness and non-contact 3D profilometry. To evaluate the wear mechanisms, the worn surfaces were analyzed by scanning electron microscopy with energy dispersive spectroscopy. The results indicated non-uniform wear damage at the rocker arm/valve interface, probably due to a misalignment of valves with respect to valve seat inserts. For rocker arms and pushrods, improper austenitization parameters and/or unsuitable design of the inductor left some free ferrite, responsible for non-compliance with required specifications for the induction hardening treatment. All worn surfaces were characterized by material removal by scuffing; initiation of fatigue cracks was also observed at the rocker arm/valve interface, and probably erosive cutting occurred at the rocker arm/pushrod interface.

Keywords Failure analysis; Diesel engine; Microstructures; Scuffing; SEM/EDS.

Corresponding Author CHIARA SOFFRITTI

Order of Authors CHIARA SOFFRITTI, Mattia Merlin, REYNA VAZQUEZ-AGUILAR, Annalisa Fortini, Gian Luca Garagnani

Suggested reviewers Omar Es-Said, Lawrence Eiselstein

Submission Files Included in this PDF

File Name [File Type]

Soffritti et al_Cover Letter_Revised.docx [Cover Letter]

Soffritti et al_Response to Reviewers.doc [Response to Reviewers]

Soffritti et al_Highlights.docx [Highlights]

Soffritti et al_Manuscript_Revised.docx [Manuscript File]

Soffritti et al_Fig1.tiff [Figure]

Soffritti et al_Fig2.tiff [Figure]

Soffritti et al_Fig3.tiff [Figure]

Soffritti et al_Fig4.tiff [Figure]

Soffritti et al_Fig5.tiff [Figure]

Soffritti et al_Fig6.tiff [Figure]

Soffritti et al_Fig7.tiff [Figure]

Soffritti et al_Fig8.tiff [Figure]

Soffritti et al_Fig9.tiff [Figure]

Soffritti et al_Fig10.tiff [Figure]

Soffritti et al_Fig11.tiff [Figure]

Soffritti et al_Table1.docx [Table]

Soffritti et al_Table2.docx [Table]

Soffritti et al_Table3.docx [Table]

Soffritti et al_Table4.docx [Table]

To view all the submission files, including those not included in the PDF, click on the manuscript title on your EVISE Homepage, then click 'Download zip file'.



UNIVERSITÀ
DEGLI STUDI
DI FERRARA
- EX LABORE FRUCTUS -

DE Department of
Engineering
Ferrara

To the Editors of
Engineering Failure Analysis

Subject: Revision of manuscript EFA_2018_415

Dear Sirs,

Thank you very much for your mail and for kindly providing comments and/or suggestions on our manuscript (EFA_2018_415). We carefully amended the manuscript according to the suggestions provided and enclose a detailed answer to the Reviewers' comments. We hope now that the manuscript is suitable for publication on your Journal.

Thank you for your kind attention and best regards,

Chiara Soffritti, PhD
Corresponding author

Department of Engineering
University of Ferrara,
Via Saragat 1, 44122 Ferrara (Italy)
E-mail: chiara.soffritti@unife.it

Ferrara, May 28th, 2018

ANSWERS TO THE REVIEWERS:

REVIEWER 1

This is an interesting paper concerned with the failure of worn valve train components of diesel engine. The components failed by excessive wear and the failure was influenced by material removal by scuffing and probably also by erosive cutting caused by free moving particles transported by the lubricant.

The paper is well written and is topical. The quality of English is good, with few or no significant grammatical errors. The conclusions are well written and are supported by the evidence presented. The paper makes an interesting and reasonably complete case study that is useful to workers in the field.

I recommend that the paper be accepted without alteration.

We thank the Reviewer for his/her favorable comments and his/her positive evaluation. We are glad for his/her appreciation of our study.

REVIEWER 2

Some minor editorial issues for instance:

274-275 "...up, producing wear particles and pits [16,22]. The intermittent propagation of fatigue cracks during each cycle has been observed in this study by the presence of fatigue striations inside pits. In all...". There one fatigue striation does not necessarily mean one load cycle. This may be better stated as "Fatigue cracking was identified by the presence of fatigue striations that indicate the periodic advance of the crack front during cyclic loading."

Following the Reviewer's suggestion, we amended the sentence as follows:

"...up, producing wear particles and pits [16,22]. Fatigue cracking has been identified by the presence of fatigue striations inside pits that indicate the periodic advance of the crack front during cyclic loading. In all...".

298 - "...the permanence of free ferrite at the induction hardened regions of rocker arms favors the..."

I believe permanence should actually be presence.

According to the Reviewer's suggestion, we amended the sentence as follows:

"...the presence of free ferrite at the induction hardened regions of rocker arms favors the...".

Highlights

- Excessive wear was detected in valve train components of a diesel engine.
- The cause was probably misalignment of valves with respect to valve seat inserts.
- The induction hardened regions of rocker arms and pushrods contained free ferrite.
- Scuffing and pits were detected at the rocker arm/valve interface.
- Scuffing and probably erosive cutting occurred at the rocker arm/pushrod interface.

1 **FAILURE ANALYSIS OF WORN VALVE TRAIN COMPONENTS OF**
2 **A FOUR-CYLINDER DIESEL ENGINE**

3
4
5 C. Soffritti^{a,*}, M. Merlin^a, R. Vazquez^a, A. Fortini^a, G.L. Garagnani^a

6
7
8 ^a Department of Engineering, University of Ferrara, Via Saragat 1, I-44122 Ferrara, Italy

9
10
11 * Corresponding author

12 Department of Engineering

13 Via Saragat 1, I-44122 Ferrara, Italy

14 Tel. +39 0532 974843

15 Fax +39 0532 974870

16 e-mail: chiara.soffritti@unife.it

17
18 Co-authors addresses: mattia.merlin@unife.it, vzqnr@unife.it, annalisa.fortini@unife.it,

19 gian.luca.garagnani@unife.it.

20
21
22 **Abstract**

23 This work investigates the causes of excessive wear occurring at the rocker arm/pushrod and rocker
24 arm/valve interfaces of a diesel engine for industrial cleaning machines, after only 1000 hours of
25 engine operation. In this engine, the recent replacement of tappets by hydraulic valve lifters not
26 only reduced the running time but also required supplementary maintenance. The chemical
27 composition of the worn components was verified by optical emission spectroscopy. The
28 microstructures, mechanical properties and surface textures were determined by optical microscopy,
29 Vickers hardness and non-contact 3D profilometry. To evaluate the wear mechanisms, the worn
30 surfaces were analyzed by scanning electron microscopy with energy dispersive spectroscopy. The
31 results indicated non-uniform wear damage at the rocker arm/valve interface, probably due to a
32 misalignment of valves with respect to valve seat inserts. For rocker arms and pushrods, improper
33 austenitization parameters and/or unsuitable design of the inductor left some free ferrite, responsible
34 for non-compliance with required specifications for the induction hardening treatment. All worn
35 surfaces were characterized by material removal by scuffing; initiation of fatigue cracks was also
36 observed at the rocker arm/valve interface, and probably erosive cutting occurred at the rocker
37 arm/pushrod interface.

38
39
40 **Keywords:** Failure analysis; Diesel engine; Microstructures; Scuffing; SEM/EDS

42 **1. Introduction**

43 Diesel engines for industrial machines generally undergo heavy using conditions, thus wear may
44 quickly jeopardize their functions unless carefully monitored and controlled. From a tribological
45 point of view, since 1950 the use of more efficient fuels and compact engines with low
46 environmental impact caused an increase of specific loads, operative velocity and temperature of all
47 components subject to wear and friction. Moreover, the use of low-viscosity lubricating oils
48 necessarily has led to a reduction of lubricating film thickness between the contact surfaces in
49 reciprocating sliding motion [1]. The cost of diesel engines has been greatly affected by the
50 increasing demand for long duration and prolonged maintenance intervals [2,3]. The increasing
51 request by laws and customers for abatement of pollutant emissions has also favored the
52 development of several technologies to eliminate soot, mostly produced by obstruction of injectors
53 and accumulation of carbon particles in manifolds [4]. Soot particulate emissions are known to
54 reduce wear and fatigue resistance of diesel engine components due to the interactions between
55 soot, metal and lubricant additives or among soot particles [5-8].

56 Recently, modeling and simulation in engine designing have emerged as important tools for
57 optimizing and predicting wear of mechanical systems under variable load and/or sliding speed. For
58 example, a model of rigid body mechanics was used to simulate the contact between the rocker arm
59 pad and the valve bridge in the cam mechanism of a diesel engine: the results showed that the
60 radius and the center position of the wear pad influenced the maximum wear depth and distribution
61 [9]. When a re-design of the tribological system is required, it is advisable to perform a control of
62 the wear mechanism in real components, where the main cause of failure is faulty manufacturing
63 involving cracks, stress concentration or improper heat treatments. The failure analysis of two
64 rocker arms from heavy duty diesel engines [10] showed a banded microstructure and the
65 spheroidization of cementite in pearlite, deriving from an unsuitable normalizing heat treatment.
66 These metallurgical defects lowered fatigue strength and favored initiation and growth of fatigue
67 cracks with multiple origins. Another study attributed to stress concentration the failure by fatigue
68 of a diesel engine rocker arm [11].

69 The present study investigates the causes of excessive wear occurring at rocker arm/pushrod and
70 rocker arm/valve interfaces of a diesel engine for industrial cleaning machines. In this engine, the
71 recent replacement of tappets by hydraulic valve lifters not only reduced the running time but also
72 required supplementary maintenance. The chemical composition of the worn components was
73 determined by optical emission spectroscopy (OES) and the microstructures were identified by
74 optical microscopy (OM). Vickers hardness and surface texture measurements were also performed.
75 Finally, to determine the wear mechanisms the worn surfaces were studied at high magnification by
76 scanning electron microscopy with energy dispersive spectroscopy (SEM/EDS).

77

78 **2. Material and methods**

79 Four pairs of rocker arms, pushrods and valves were collected from a four-cylinder diesel engine
80 for industrial cleaning machines. In this engine, all clearances at the induction hardened regions
81 were set back to zero due to excessive wear after only 1000 hours of engine operation. A schematic
82 representation of the outlet/inlet rocker arm and parts of the pushrod and exhaust/intake valve is
83 shown in Fig. 1, together with an indication of the regions with worn surfaces. The outlet/inlet
84 rocker arm, pushrods and the exhaust and intake valves were prepared for analysis of the chemical
85 composition of the steel types by optical emission spectroscopy (OES) through a SPECTROLAB
86 analyzer (SPECTRO Analytical Instruments GmbH, Kleve, Germany). The details of chemical

87 composition of the different steel types are shown in Table 1. In order to increase surface hardness
88 and contact fatigue resistance, in this engine some regions of the outlet/inlet rocker arm pad, the
89 outlet/inlet rocker arm pivot socket, the pushrod ball ends and the exhaust/intake valve stem tip
90 were induction hardened. The required specifications concerning Rockwell hardness values (HRC)
91 and effective depth of the regions undergoing induction hardening treatment are shown in Table 2.
92 The worn surfaces were first observed by a Leica MZ6 (Leica, Wetzlar, Germany)
93 stereomicroscope. To determine the microstructures of alloys, longitudinal sections (parallel to the
94 metal surface) and cross-sections (perpendicular to the metal surface) of the samples were prepared,
95 mounted in resin, polished and analyzed by a Leica MEF4M optical microscope (Leica).
96 Microstructural investigations were carried out after chemical etching by Nital 4 (4% nitric acid in
97 ethanol) under the same optical microscope. The micrographs of the cross-sections were processed
98 by Leica Application Suite (LAS, Leica) image analysis software to evaluate the area fraction of
99 metallographic phases occurring in the induction hardened regions. A mean of 15 micrographs were
100 analyzed for each component. On the cross-sections, Vickers hardness measurements (HV1) under
101 1000 g_f load and 15 s loading time were performed in triplicate at increasing distances from the
102 worn surfaces (0.2-4.0 mm) by a Future-Tech FM-110 Vickers microindenter (Future-Tech Corp.,
103 Kawasaki, Japan). The Vickers hardness values were then converted in Rockwell hardness values
104 according to the standard ASTM E140-12 to verify the required specifications for the induction
105 hardening treatment.

106 The 3D surface textures of the outlet/inlet rocker arm pads and exhaust/intake valve stem tips were
107 evaluated by a Talysurf CCI-Lite non-contact 3D profilometer (Taylor-Hobson, Leicester, UK).
108 The 3D height parameters Sa (arithmetical mean height of the surface), Sq (root mean square height
109 of the surface), Ssk (skewness) and Sku (kurtosis) were determined according to the standard ISO
110 25178. Each value was an average of twenty measurements performed on 1.0x1.0 mm² areas of
111 both fresh and worn surfaces. To identify the wear mechanisms the worn surfaces were
112 characterized by a Zeiss EVO MA 15 (Zeiss, Oberkochen, Germany) scanning electron microscopy
113 (SEM), equipped with an Oxford X-Max 50 (Oxford Instruments, Abingdon-on-Thames, UK)
114 energy dispersive microprobe for semi-quantitative analyses (EDS). The SEM micrographs were
115 recorded in secondary electron imaging (SEI-SEM) and back-scattered electron (BSE-SEM) mode.
116

117 **3. Results**

118 The stereomicroscopy images representing the excessive wear at the induction hardened regions are
119 shown in Fig. 2a-f. The extent of wear on the surface of the outlet rocker arm pad (Fig. 2(a)) was
120 greater than that on the surface of the inlet rocker arm pad (Fig. 2(b)). At the exhaust side, the wear
121 damage was slightly offset from the center of the outlet rocker arm pad; conversely, at the intake
122 side, the wear damage was located at the center of the inlet rocker arm pad. At exhaust and intake
123 sides, the depth of wear was higher at the surface regions respectively located at the opposite
124 directions of the intake and of the exhaust side (white arrows in Fig. 2(a) and (b)). From a
125 morphological point of view, the worn surface of the outlet/inlet rocker arm pad could be divided
126 into two zones: the first one (Fig. 2(a), red outline) was shiny with scuffing appearance, whereas the
127 second one (Fig. 2(a), orange outline) was matted with numerous pits uniformly distributed over the
128 worn surface. Moreover, on the worn surface of the inlet rocker arm pad (Fig. 2(b)) several
129 concentric circles were visible. The morphology of the worn surfaces of exhaust and intake valve
130 stem tips was characterized by the same features observed on the worn surface of the outlet/inlet
131 rocker arm pad (Fig. 2(c) and (d)). Once again, at the center of the intake valve stem tip many

132 concentric circles could be observed (Fig. 2(d)). Concerning the outlet and inlet rocker arm pivot
133 sockets, excessive wear involved material removal with grooves and scratch marks, mostly parallel
134 and distributed over the worn surfaces (Fig. 2(e) and (f)).

135 An example of the microstructure observed on the cross-section of the inlet rocker arm pivot socket
136 is shown in Fig. 3a-c. Beginning from the worn surface inwards, the microstructure of the induction
137 hardened region was bainitic-martensitic with some free ferrite (Fig. 3(a)), and that of the transition
138 region between the induction hardened layer and the unaffected core was upper bainitic with
139 troostite, again with some free ferrite (Fig. 3(b)). The coarse microstructure of the unaffected core
140 was ferritic-pearlitic (Fig. 3(c)). The microstructures of the cross-sections of the outlet rocker arm
141 pivot socket and of the outlet/inlet rocker arm pad were similar. The pushrod ball ends were totally
142 induction hardened, thus the microstructure was uniformly bainitic-martensitic with some free
143 ferrite. The mean area fractions in percentage of bainite-martensite and free ferrite occurring in the
144 induction hardened regions of the outlet/inlet rocker arm pad, outlet/inlet rocker arm pivot socket
145 and pushrod ball ends are shown in Table 3. The area fraction of free ferrite was the highest
146 ($\cong 10\%$) in the outlet/inlet rocker arm pivot socket, while in the outlet/inlet rocker arm pad and
147 pushrod ball ends ranged from 3 to 6%.

148 An example of the banded microstructure observed on a cross-section of the intake valve stem tip is
149 shown in Fig. 4a-b. The microstructure of the induction hardened region was martensitic with large
150 primary carbides oriented along the working direction and small secondary carbides located along
151 the grain boundaries (Fig. 4(a)). The microstructure of the unaffected core was composed of fine
152 pearlite and globular cementite particles, with a greater amount of oriented large primary carbides
153 and segregated secondary carbides (Fig. 4(b)). The microstructures of the cross-sections of the
154 exhaust valve stem tip were similar.

155 The Vickers hardness profiles of the cross-sections of inlet rocker arm pad, inlet rocker arm pivot
156 socket, pushrod ball ends, exhaust valve stem tip and intake valve stem tip at different distances
157 from the worn surfaces are displayed in Fig. 5a-e. For the inlet rocker arm pad and inlet rocker arm
158 pivot socket, the hardness profiles did not comply with the specifications concerning HRC values
159 and effective depth required at the induction hardened regions: for the inlet rocker arm pad, the
160 required HRC values (55-59 HRC, corresponding to 595-674 HV1) were maintained only up to
161 about 0.5 mm in depth (Fig. 5(a)); for the inlet rocker arm pivot socket (Fig. 5(b)), the HRC values
162 were not the required ones and no decrease in hardness was registered from the worn surface to the
163 core of material. Moreover, the hardness profile of the inlet rocker arm pivot socket (Fig. 5(b))
164 showed marked discontinuities between 1.1 and 2.6 mm in depth. Overall, the Vickers hardness
165 profiles showed that HRC values and effective depth were below the required specifications for all
166 pairs of rocker arms.

167 The Vickers hardness values of cross-sections of all pushrods (Fig. 5(c)) were more or less constant,
168 but the related HRC values were below the minimum requirement for the induction hardened region
169 (58 HRC, corresponding to 653 HV1).

170 For all exhaust and intake valves (Figs. 5(d) and (e)), the HRC values and effective depth at the
171 induction hardened regions satisfied the required specifications.

172 Examples of 3D surface textures of the worn surfaces of the outlet/inlet rocker arm pad and
173 exhaust/intake valve stem tip are shown as 3D isometric views in Fig. 6a-d. The 3D isometric view
174 of the surface of the inlet rocker arm pad was apparently less worn in comparison to that of the
175 other three components. The mean values of the 3D height parameters S_a , S_q , S_{sk} and S_{ku} of the
176 fresh and worn surfaces of the outlet/inlet rocker arm pad and exhaust/intake valve stem tip are

177 shown in Table 4. For the outlet rocker arm pad and the exhaust/intake valve stem tip, the Sa and Sq
178 values of the worn surfaces were higher than those of the fresh ones; on the contrary, as previously
179 mentioned, those of the inlet rocker arm pad were lower than those of the fresh ones. The skewness
180 (Ssk) of the fresh surfaces was negative, but that of the worn surfaces became positive for all
181 components except the exhaust valve stem tip. Concerning the kurtosis (Sku), this parameter
182 exhibited a different behavior: for the outlet/inlet rocker arm pad, Sku values of the fresh surfaces
183 were higher than those of the worn surfaces ($Sku < 3.00$), but those of the exhaust/intake valve stem
184 tip were lower than those of the worn surfaces ($Sku > 3.00$).

185 The SEI-SEM micrographs of the worn surfaces of pushrod ball ends are shown in Fig. 7a-c. The
186 morphology of the worn surface of pushrod ball ends (Fig. 7(a)) was characterized by two features:
187 material removal by scuffing (Fig. 7(b)) and probably by erosive cutting (Fig. 7(c)). The material
188 removal by scuffing was associated with linear grooves and scratch marks, mostly parallel and
189 uniformly distributed over a wide area of the worn surface. All plastically deformed material was
190 mostly removed by the surface during motion and to a minor extent it accumulated to the sides of
191 the grooves. The erosive cutting generated a series of ripples oriented along the direction of grooves
192 and limited to a narrow region of the worn surface. For all pairs of pushrod ball ends and rocker
193 arm pivot sockets the morphology of the worn surfaces was similar.

194 The SEM/EDS analysis of the shiny area observed on the worn surface of outlet rocker arm pad
195 (Fig. 2(a)) indicated material removal by scuffing, as in pushrod ball ends. Concerning the matted
196 area observed on the worn surface of the same component, the SEI-SEM micrographs showed the
197 presence of numerous pits, ranging in size from a few tens of micrometers to several hundred
198 micrometers (Fig. 8(a)). At higher magnification, subsurface interconnected microcracks and
199 fatigue striations were visible inside the pits (Fig. 8(b)), together with wear particles in the form of
200 spherical agglomerates (Fig. 9 (left)). The semi-quantitative EDS analysis of spherical agglomerates
201 indicated the presence of high percentages of oxygen and iron, and traces of manganese, silicon and
202 calcium (Fig. 9 (right)). For all pairs of outlet/inlet rocker arm pads the morphology of the worn
203 surfaces was similar.

204 The morphology of the worn surfaces of all pairs of exhaust/intake valve stem tips was
205 characterized by the same features identified on the worn surfaces of the outlet/inlet rocker arm
206 pads, but the grooves, scratch marks and pits were less marked (Figs. 10(a) and (b)).

207 These worn surfaces were also analyzed by SEM/EDS in back-scattered electron mode (BSE-
208 SEM), followed by semi-quantitative EDS analysis. In all surfaces, dark and light contrast areas
209 could be identified (Fig. 11 (left)): the EDS analysis revealed the presence of sulfur, phosphorous,
210 calcium and zinc in the dark contrast areas, which was related to the residues of lubricant additives
211 (Fig. 11 (right)).

212

213 **4. Discussion**

214 A failure analysis process was performed to investigate the excessive wear occurring at rocker
215 arm/pushrod and rocker arm/valve interfaces of a diesel engine for industrial cleaning machines.
216 The worn surfaces of the outlet rocker arm pad show a high wear damage due to the harsh chemical
217 environment and high temperatures occurring at the exhaust side. For the outlet/inlet rocker arm
218 pad, the position of the wear tracks and the higher wear depth at the surface regions located at the
219 opposite direction of the intake/exhaust side suggest a misalignment of the valves with respect to
220 the valve seat inserts. The role of valve seat insert is to avoid direct contact of the valve with the
221 cylinder head, absorbing part of the combustion heat transferred to the valve and passing it onto the

222 cylinder head [12]. Slight misalignments caused by small differences in roundness or valve seating
223 face angles may lead to uneven wear and non-uniform heat transfer from the valve head to the seat
224 insert. Eventually, misalignments occurring during assemblage may cause the valve recession into
225 the seat insert [13,14]. The absence of concentric circles on the wear surfaces of the outlet rocker
226 arm pad and exhaust valve stem tip, associated to non-rotating valve during engine operation,
227 support the hypothesis of misalignment, although the concentric circles could have been removed
228 by scuffing at the rocker arm/valve interface. On the other hand, the concentric circles are visible on
229 the worn surfaces of the inlet rocker arm pad and intake valve stem tip, thus the valve rotates more
230 or less correctly, reducing wear and friction [15].

231 The optical microscope images show some free ferrite at the induction hardened regions of the
232 outlet/inlet rocker arm and pushrods. The outlet/inlet rocker arm pivot socket contained the highest
233 percentage of free ferrite ($\approx 10\%$), while the outlet/inlet rocker arm pad and pushrod ball ends had
234 percentages ranging from 3 to 6%. The induction hardening treatment should involve a rapid
235 austenitization of the surface of a steel part through the magnetic field of a water-cooled copper coil
236 (inductor), and then quenching by spraying of water or other fluids [16]. The essential issue is rapid
237 heating, which shifts to higher values the start temperature for austenite formation (A_{c1}) and the
238 temperature at which transformation of ferrite to austenite is completed (A_{c3}). More specifically,
239 A_{c1} is a function of the heating rate, of the microstructure prior to induction hardening and of the
240 chemical composition of steel [17]. For the outlet/inlet rocker arm and pushrods composed of
241 hypoeutectoid carbon steels, the starting microstructures consisted of pearlite and proeutectoid
242 ferrite. When A_{c1} is reached, these phases initiate the transformation into austenite, which occurs
243 more rapidly in pearlite. The rates of austenitization depend on size and shape of the workpieces, so
244 the final microstructure and grain size distribution will be non-uniform from the surface to the core
245 of material [17]. Previous research showed that A_{c1} and A_{c3} temperatures were significantly higher
246 for an initial microstructure of ferritic-pearlitic type than for a tempered martensitic one [18]. In the
247 present study, for all pairs of rocker arms unsuitable austenitization temperatures and times left
248 some of the proeutectoid ferrite untransformed, in the form of free ferrite. The presence of free
249 ferrite was also probably favored by a design of the inductor shape unsuitable for the induction
250 hardened regions, especially for those of the rocker arm pivot sockets. Improper austenitization
251 parameters and/or unsuitable design of the inductor shape could therefore be responsible for the
252 non-compliance with the required specifications for the induction hardening treatment.

253 For all components, the scanning electron microscope analyses revealed linear grooves and scratch
254 marks which were mostly parallel and uniformly distributed over wide areas of the worn surfaces.
255 These data suggest scuffing as the main failure mode. Scuffing is known to be promoted by the
256 presence of free ferrite in the microstructure, while pearlite tends to retard it [19]. In boundary
257 lubrication conditions, it is associated with the progressive desorption of the lubricant at the contact
258 interface, depending on the interaction among polar constituents of lubricants and surfaces, and on
259 the rate of destruction and reforming of protective oxides [19]. When scuffing occurs, a severe
260 surface destruction process is established [20,21], as confirmed by the increase in Sa, Sq and Ssk
261 parameters from fresh to worn surfaces in the present study. Concerning the worn surfaces of
262 exhaust/intake valve stem tip, the material removal by scuffing at the rocker arm/valve interface
263 could be accelerated by the large primary carbides surfacing at the contact interface, identified by
264 optical microscope observations, and by the Sku values > 3.00 , indicating a surface with sharp
265 peaks and deep valleys [20].

266 The SEM/EDS analyses of the worn surfaces at the rocker arm/valve interface also revealed the
267 presence of numerous pits with subsurface interconnected microcracks and fatigue striations. The
268 pits contained wear particles in the form of spherical agglomerates identified as iron oxides by EDS
269 analyses. Pitting is the consequence of fatigue affecting surfaces characterized by non-conformal
270 contacts [22]. In these conditions, fatigue cracks may nucleate either at the surface or at stress
271 concentration points at small depths below the surface, such as non-metallic inclusions, precipitates
272 or pre-existing flaws, and/or soft spots in the microstructure, for example in regions where free
273 ferrite is present. Cracks then propagate towards the interior of the material and eventually curve
274 up, producing wear particles and pits [16,22]. **Fatigue cracking has been identified by the presence
275 of fatigue striations inside pits that indicate the periodic advance of the crack front during cyclic
276 loading.** In all surfaces, residues of lubricant additive containing sulfur, phosphorous, calcium and
277 zinc were detected, attributable to Zinc Dialkyl Dithio Phosphate (ZDDP) anti-wear additives.
278 Previous research showed that ZDDP additives may promote fatigue crack initiation by preventing
279 surface roughness reduction during running-in, or by creating corrosion pits on the contact surfaces
280 [23,24]. Due to the high pressure at these surfaces, the lubricant flows into cracks, exerting a
281 pumping effect which increases the driving force for crack propagation [25].
282 Finally, in some narrow regions of the worn surfaces of pushrod ball ends and rocker arm pivot
283 sockets, a series of ripples oriented along the direction of grooves were observed, generated by
284 erosive cutting. For ductile materials, these ripples may be the product of free moving particles
285 transported by the lubricant and wearing out the softer surface [19].
286

287 **5. Conclusions**

288 A failure analysis of rocker arms, pushrods and valves collected from a four-cylinder diesel engine
289 for industrial cleaning machines was performed to investigate the causes of excessive wear
290 occurring at the rocker arm/pushrod and rocker arm/valve interfaces, after only 1000 hours of
291 engine operation. Based on the results, the following conclusions can be drawn:

- 292 - the non-uniform wear damage detected at the rocker arm/valve interface suggests a
293 misalignment of the valves with respect to the valve seat inserts;
- 294 - improper austenitization parameters and/or unsuitable design of the inductor shape left some
295 free ferrite at the induction hardened regions of the rocker arms and pushrods. This faulty
296 procedure could be responsible for non-compliance with required specifications for the
297 induction hardening treatment;
- 298 - **the presence of free ferrite at the induction hardened regions of rocker arms favors** the
299 material removal by scuffing and the initiation of fatigue cracks at the rocker arm/valve
300 interface. The propagation of cracks is promoted by the pumping effect exerted by the
301 ZDDP anti-wear additives;
- 302 - at the rocker arm/pushrod interface the wear damage is caused by material removal by
303 scuffing and probably also by erosive cutting caused by free moving particles transported by
304 the lubricant.

305 **Acknowledgements**

306 The authors thank Dr Milvia Chicca for help in revising the manuscript. This work was supported
307 by the Department of Engineering, University of Ferrara (Ferrara, Italy), grant n. 2238/2010.
308
309

310 **References**

- 311 [1] M. Priest, C.M. Taylor, Automotive engine tribology – approaching the surface, *Wear* 241
312 (2000) 53–65.
- 313 [2] M. Mackaldener, Simulations in engine design with focus on tribology, Proceedings of the 10th
314 Nordic Symposium on Tribology, Nordtrib 2002, Stockholm, Sweden, (2002).
- 315 [3] R. Lewis, R.S. Dwyer-Joyce, G. Josey, Design and development of a bench test rig for
316 investigating diesel engine inlet valve and seat insert wear, Proceedings of Austrib '98, Brisbane,
317 Australia, (1998).
- 318 [4] S. George, S. Balla, M. Gautam, Effect of diesel soot contaminated oil on engine wear, *Wear*
319 262 (2007) 1113–1122.
- 320 [5] S. Antusch, M. Dienwiebel, E. Nold, P. Albers, U. Spicher, M. Scherge, On the tribochemical
321 action of engine soot, *Wear* 269 (2010) 1–12.
- 322 [6] M. Gautam, K. Chitoor, M. Durbha, J.C. Summers, Effect of diesel soot contaminated oil on
323 engine wear – investigation of novel oil formulations, *Tribol. Int.* 32 (1999) 687–699.
- 324 [7] P. Diatto, M. Anzani, L. Tinucci, G. Tripaldi, A. Vettor, Investigation on soot dispersant
325 properties and wear effects in the boundary lubrication regime, *Tribology Series* 36 (1999) 809–
326 819.
- 327 [8] E.A. Khorshid, A.M. Nawwar, A review of the effect of sand dust and filtration on automobile
328 engine wear, *Wear* 141 (1991) 349–371.
- 329 [9] C. Spiegelberg, S. Andersson, Simulation of friction and wear in the contact between the valve
330 bridge and rocker arm pad in a cam mechanism, *Wear* 261 (2005) 58–67.
- 331 [10] Z.W. Yu, X.L. Xu, Failure analysis of diesel engine rocker arms, *Eng. Fail. Anal.* 13 (2006)
332 598–605.
- 333 [11] M.M. Muhammad, M.C. Isa, M.S.D. Yati, S.R.S. Bakar, I.M. Noor, Failure analysis of a diesel
334 engine rocker arm, *Def. S&T Tech. Bull.* 3 (2010) 78–84.
- 335 [12] K. Mollenhauer, H. Tschöke, Handbook of diesel engines, Springer-Verlag GmbH, Berlin,
336 2010.
- 337 [13] P. Forsberg, P. Hollman, S. Jacobson, Wear mechanism study of exhaust valve system in
338 modern heavy duty combustion engines, *Wear* 271 (2011) 2477–2484.
- 339 [14] Y.S. Wang, S. Narasimhan, J.M. Larson, S.K. Schaefer, Wear and wear mechanism simulation
340 of heavy-duty engine intake valve and seat inserts, *J. Mater. Eng. Perform.* 7 (1998) 53–65.
- 341 [15] L. Jelenschi, C. Cofaru, G. Sandu, M. Aleonte, State of the art of engine valve and tappet
342 rotation, *Bulletin of the Transilvania University of Braşov, Series I: Engineering Sciences* 4 (2011)
343 19–24.
- 344 [16] G. Straffelini, Friction and wear. Methodologies for design and control, Springer International
345 Publishing AG, Cham (ZG), Switzerland, 2015.
- 346 [17] B.J. Yang, A. Hattiangadi, W.Z. Li, G.F. Zhou, T.E. McGreevy, Simulation of steel
347 microstructure evolution during induction heating, *Mat. Sci. Eng. A* 527 (2010) 2978–2984.
- 348 [18] K.D. Clarke, C.J. Van Tyne, C.J. Vigil, R.E. Hackenberg, Induction hardening 5150 steel:
349 effects of initial microstructure and heating rate, *J. Mater. Eng. Perform.* 20 (2011) 161–168.
- 350 [19] R. Chattopadhyay, Surface wear. Analysis, treatment, and prevention, ASM International,
351 Materials Park, Ohio, 2001.
- 352 [20] Y. Jeng, Impact of plateaued surfaces on tribological performance, *Tribol. T.* 39 (1996) 354–
353 361.

- 354 [21] Y.S. Kang, C.H. Hager, R.D. Evans, Effects of skewed surface textures on lubricant film
355 thickness and traction, *Tribol. T.* 58 397–406.
- 356 [22] A. Terrin, C. Dengo, G. Meneghetti, Experimental analysis of contact fatigue damage in case
357 hardened gears for off-highway axles, *Eng. Fail. Anal.* 76 (2017) 10–26.
- 358 [23] A.A. Torrance, J.E. Morgan, G.T.Y. Wan, An additive's influence on the pitting and wear
359 of ball bearing steel, *Wear* 192 (1996) 66–73.
- 360 [24] E. Lainé, A.V. Olver, M.F. Lekstrom, B.A. Shollock, T.A. Beveridge, D.Y. Hua, The effect of
361 a friction modifier additive on micropitting, *Tribol. T.* 52 (2009) 526–533.
- 362 [25] B. L'Hostis, C. Minfray, M. Frégonèse, C. Verdu, B. Ter-Ovanessian, B. Vacher, T. Le
363 Mogne, F. Jarnias, A. Da-Costa D'Ambros, Influence of lubricant formulation on rolling contact
364 fatigue of gears – interaction of lubricant additives with fatigue cracks, *Wear* 382–383 (2017) 113–
365 122.
- 366

367 **FIGURE CAPTIONS**

368

369 **Fig. 1.** Schematic representation of outlet/inlet rocker arm and parts of pushrod and exhaust/intake
370 valve. The dashed lines enclose the regions with worn surfaces. A: outlet/inlet rocker arm pad. B:
371 exhaust/intake valve stem tip. C: outlet/inlet rocker arm pivot socket. D: pushrod ball end.

372

373 **Fig. 2.** Stereomicroscopic images representing the excessive wear at the induction hardened
374 regions: (a) outlet rocker arm pad; (b) inlet rocker arm pad; (c) exhaust valve stem tip; (d) intake
375 valve stem tip; (e) outlet rocker arm pivot socket; (f) inlet rocker arm pivot socket. In (a) and (b)
376 white arrows indicate the surface regions respectively located at the opposite directions of the
377 intake and of the exhaust side, and in (a) the red and orange dashed lines enclose regions with
378 different morphological features.

379

380 **Fig. 3.** Optical micrographs of the microstructure observed in cross-sections of the inlet rocker arm
381 pivot socket. From the worn surface inwards: (a) induction hardened region with free ferrite (white
382 areas); (b) transition region between the induction hardened layer and the unaffected core, with
383 troostite (dark grey clusters) and free ferrite (white areas); (c) unaffected core.

384

385 **Fig. 4.** Optical micrographs of the microstructure observed in cross-sections of the intake valve
386 stem tip. From the worn surface inwards: induction hardened region (a) and unaffected core (b)
387 with primary and secondary carbides (white areas).

388

389 **Fig. 5.** Vickers hardness profiles of the cross-sections of inlet rocker arm pad (a), inlet rocker arm
390 pivot socket (b), pushrod ball ends (c), exhaust valve stem tip (d) and intake valve stem tip (e), at a
391 distance (mm) from the worn surfaces. Error bars represent standard deviation.

392

393 **Fig. 6.** The 3D isometric views of the worn surfaces of the outlet rocker arm pad (a), inlet rocker arm
394 pad (b), exhaust valve stem tip (c) and intake valve stem tip (d).

395

396 **Fig. 7.** SEI-EM micrographs of the worn surface of pushrod ball ends: (a) overview of worn
397 surface; (b) detail of the surface showing material removal by scuffing with parallel grooves and
398 scratch marks; (c) detail of the surface showing erosive cutting with ripples oriented along the
399 direction of grooves.

400

401 **Fig. 8.** SEI-SEM micrographs of the matted area with pits observed on the worn surface of outlet
402 rocker arm pad: (a) overview of pits; (b) details of the subsurface of a pit showing interconnected
403 microcracks and fatigue striations.

404


405 **Fig. 9.** SEI-SEM micrograph of a wear particle in form of a spherical agglomerate detected inside a
406 pit of the matted area on the worn surface of outlet rocker arm pad (left) and semi-quantitative EDS
407 analysis of the spherical agglomerate (right).







408




409 **Fig. 10.** SEI-SEM micrographs of the worn surface of an exhaust valve stem tip: (a) detail of
410 grooves and scratch marks; (b) detail of pits.



411


412 **Fig. 11.** BSE-SEM micrograph of the worn surface of an intake valve stem tip (left) and semi-
413 quantitative EDS analyses of dark (A) and light (B) contrast areas in the same surface (right).














(a)




(b)







(c)






(d)




(e)









(a)




(a)



5 μm





25 μm





Table 1 Chemical composition (wt%) of steel types of the worn components of a four-cylinder diesel engine for industrial cleaning machines.

Component	C	S	Mn	Si	Cr	Ni	Mo	Cu	Fe
Outlet/Inlet Rocker arm	0.42	0.020	0.71	0.16	0.13	0.08	< 0.03	0.17	balance
Pushrods	0.37	< 0.002	0.67	0.20	0.19	0.07	0.06	0.14	balance
Exhaust valve	0.50	0.006	0.47	3.34	7.68	0.13	0.03	0.03	balance
Intake valve	0.88	< 0.002	0.60	0.61	16.15	0.13	1.75	0.05	balance

Table 2 Required specifications concerning Rockwell hardness values (HRC) and effective depth (mm) of the regions undergoing induction hardening treatment.

Induction hardened region	HRC	Effective depth (mm)
Outlet/Inlet Rocker arm pad	55-59	2.0
Outlet/Inlet Rocker arm pivot socket	55-59	2.0
Pushrod ball ends	≥ 58	-*
Exhaust valve stem tip	≥ 54	0.8
Intake valve stem tip	≥ 48	0.8

* No effective depth could be established because the pushrod ball ends were totally induction hardened.

Table 3 Mean area fractions (%) \pm standard deviation (SD) of bainite-martensite and free ferrite in the induction hardened regions of the outlet/inlet rocker arm pad, outlet/inlet rocker arm pivot socket and pushrod ball ends. Each area fraction was evaluated on wide areas (1.0x0.5 mm²) of the cross-sections by image analysis software.

Induction hardened region	Bainite-martensite		Free ferrite	
	Mean	SD	Mean	SD
Outlet rocker arm pad	95.12	0.78	4.88	0.78
Inlet rocker arm pad	94.26	0.44	5.74	0.44
Outlet rocker arm pivot socket	90.10	0.97	9.90	0.97
Inlet rocker arm pivot socket	90.35	0.72	9.65	0.72
Pushrod ball ends	96.17	0.69	3.83	0.69

Table 4 Mean Sa (μm), Sq (μm), Ssk and Sku \pm standard deviation (SD) of the fresh and worn surfaces of the outlet/inlet rocker arm pad and exhaust/intake valve stem tip.

Induction hardened region		Sa (μm)		Sq (μm)		Ssk		Sku	
		Mean	SD	Mean	SD	Mean	SD	Mean	SD
Outlet rocker arm pad	Fresh surface	0.78	0.07	1.00	0.09	-0.56	0.26	3.59	0.55
	Worn surface	1.49	0.26	1.81	0.30	0.14	0.21	2.57	0.21
Inlet rocker arm pad	Fresh surface	0.74	0.05	0.91	0.07	-0.42	0.14	2.87	0.42
	Worn surface	0.42	0.12	0.50	0.16	0.27	0.15	2.46	0.24
Exhaust valve stem tip	Fresh surface	0.63	0.05	0.81	0.08	-0.30	0.17	2.22	0.20
	Worn surface	1.16	0.21	1.47	0.30	-0.26	0.51	3.74	1.10
Intake valve stem tip	Fresh surface	0.65	0.04	0.86	0.05	-0.35	0.15	2.25	0.21
	Worn surface	0.72	0.13	0.90	0.14	0.18	0.40	3.10	0.45